## NATIONAL ORGANIZATION

## SONS OF UNION VETERANS OF THE CIVIL WAR

## CIVIL WAR MEMORIAL ASSESSMENT FORM

۲	LEASE	:	
	T		_

Type or print, using a ball-point pen, when filling out this form. Legibility is critical.

<ul> <li>Do not guess at the information. An answ</li> </ul>	er of, "Unknown," is mo	ore helpful.
<ul> <li>Include a photograph of each viewable side a</li> </ul>	and label it with name & d	
Type of Memorial		- Thank You.
Type of Memorial	à .	
Monument with Sculpture	Monument with	
Monument without Sculpture	X Historical Marke	r Plaque
<u>Affiliation</u>		
G.A.R. (Post Name & No	<b>)</b>	MOLLUS
W.R.C. (Corps Name & No.	)	Other Allied Order
SUVCW (Camp Name & No	)	(Please describe below)
DUVCW (lent Name & No.	<b>)</b>	(**************************************
X Other: Rotary International		
Original Dedication Date 1945-1955 local paper's article that would have information on the first of Please submit a copy of your findings with full identification of	Please consult any/all dedication ceremony and/or oth f the paper & date of publication	newspaper archives for a her facts on the memorial. n. Thank you.
Location The Memorial is currently located at: Street/Road address or site location SE Corner	Broadway and Cordelia (W89°:	32'41" N37°18'46")
City/Village Cape Girardeau Township		
	Odding	pe characaa, mo
The front of the Memorial faces: X North	South Ea	st West
Government Body, Agency, or Individual Owner (	of private cemetery that Mer	morial is located in)
Name Unknown, believe it is on Methodist Church property	Dept./Div.	nonaris located III)
Street Address		
City	State Zip Coo	de de
Contact Person	Telephone ( )_	
If the Memorial has been moved, please list fo Not Applicaber		
Physical Details  Material of Monument or base under a Southture or Connect	24 ¥ 0	
Material of Monument or base under a Sculpture or Cannon = f known, name specific material (color of granite, n	marble, etc.)	letal Undetermined

Material of the Scull f known, name spect of the Sculpture is of	ific material (c	olor of gra	nite, marble, et		al Undetermined
Material of Plaque	or Historical I	Marker / T	Fablet = bronze	9	
Markings on muzzle	e = N/a				ance Listing to confirm
Markings on Left Tr	runion		Right	Trunion	
Is inert ammunition	a part of the	Memoria	l? If so	o, describe	)
Approximate Dime Monument or Base: Sculpture:	ensions (indi Height 2 1/2 Height	cate unit 2 t Widt Widt	of measure) - h <u>2 1/2 feet</u> Dep h Dep	taken from oth 2 1/2 feet oth	m tallest / widest points or Diameter or Diameter
sheet of paper for	each statue a	and attac s/impleme	to this form	. Please	rmation on a separate describe the "pose" of your photos become
Markings/Inscripti Maker or Fabricator	· · · · · · · · · · · · · · · · · · ·				t, base, sculpture) und
The "Dedication Te	xt" is formed:	cut i	into material	× raised	d up from material face
Record the text (indicated) 1863 THE BATTLE OF CAPE					ditional sheet if necessary. e left flank; and Perryville Road the
right flank; of the Union forces	commanded by Brig	. Gen. John H.	McNeil. A sharp, bloc	ody attack by Co	onfederates led by Gen. Joe Shelby
from the command of Gen.	John S. Marmaduk	ke was repuls	ed on April 26, 1863	3. This engage	ement came to be known as the
Battle of Cape Girardeau.					
Profile of Indian Chief atop	plaque.				
Rotary International symbol at	bottom.				
Environmental (The general vicinity and in		surrounding	a memorial can pla	y a maior role	e in its overall condition )
				.,	
Type of Location					
Cemetery		-	ark		Plaza/Courtyard
"Town Square"		-	ost Office		School
Municipal Build	ing		tate Capitol		Other: Streetside
Courthouse			ollege Campu	IS	M. 44-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
Traffic Circle		1	ihrary		

General Vicinity  Rural (low population, open land)  Town	Suburban (residential, Urban / Metropolitan	near city)
Immediate Locale (check as many as may apply)  Industrial  X Street/Roadside within 20 feet  Protected from the elements (canopy or enclosure protected from the public (fence or other barrier Any other significant environmental factor		nging branches
Condition Information	À.	
<b>Structural Condition</b> (check as many as may apply The following section applies to Monuments with Sculpture including the base for Monuments with Cannon. Instability in the by a number of factors. Indicators may be obvious or subtle base.	ire, and Monuments with	can be detected
	Sculpture	Base
If hollow, is the internal support unstable/exposed?  (look for signs of exterior rust)	no	no
Any evidence of structural instability?	no	no
(look for cracked joints, missing mortar or caulking or plant growth)  Any broken or missing parts?  (look for elements (i.e., sword, musket, hands, arms, etc missing due to vandalism, fluctuating weather conditions, etc.)	no	<u></u>
Any cracks, splits, breaks or holes?  (also look for signs of uneven stress & weakness in the material)	no	no
Surface Appearance (check as many as may apply	) Sculpture	Base
Black crusting White crusting		-
Etched, pitted, or otherwise corroded (on metal)		-
Metallic staining (run-off from copper, iron, etc.)	-	
Organic growth (moss, algae, lichen or vines)	-	-
Chalky or powdery stone	-	
Granular eroding of stone		-
Spalling of stone (surface splitting off)		
Droppings (bird, animal, insect remains) Other (e.g., spray paint graffiti) - Please describe	·	
Does water collect in recessed areas of the Memorial?	Yes _X_NoL	Jnable to tell

Surface Coating	
Does there appear to be a coating?	Yes X No Unable to determine
If known, identify type of coating.  Gilded Painted Varnishe	d Waxed Unable to determine
Is the coating in good condition? Yes	
vec	
<b>Basic Surface Condition Assessment</b> (d	check <u>one</u> )
In your opinion, what is the general appear X Well maintained Would benefit from treatment	ance or condition of the Memorial?In urgent need of treatment Unable to determine
Overall Description	
Briefly describe the Memorial (affiliation / overall co	ondition & any concern not already touched on) .
	<u>i</u>
Supplemental Background Information	
Mamarial will be welcomed. Please label and	lal information you can provide on the described h account with its source (author, title, publisher,
	the points listed on this questionnaire, plus any
previous conservation treatments - or efforts to	
provided deficiel validity is defined to	raise meney for a cument.
Inspector Identification	
Date of On-site Survey 19 June 2006	
Your Name Walter E Busch, Commander, US Grant Camp #60	3, Dept of Missouri
Address PO Box 509	City Pilot Knob
State Zip Code _63663	Telephone ( 314 ) 630-8407
Please send this completed form to:	
·	
Todd A. Shillington, PDC	
Todd A. Shillington, PDC 15 Park Place	
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	
Todd A. Shillington, PDC 15 Park Place	
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022 (585) 638-5929	

