NATIONAL ORGANIZATION

SONS OF UNION VETERANS OF THE CIVIL WAR

CIVIL WAR MEMORIAL ASSESSMENT FORM

P	1	F	Δ	S	F	•
	_	_	_		_	

- Type or print, using a ball-point pen, when filling out this form. Legibility is critical.
- Do not guess at the information. An answer of, "Unknown," is more helpful.

 Include a photograph of each viewable side 		•
annual a priotograph of cacil revalue side	and laborit with hame a dir	- Thank You.
Type of Memorial		
Monument with Sculpture	Monument with C	Cannon
Monument without Sculpture	X Historical Marker	
Thomas and an analysis of the second of the	T I I I I I I I I I I I I I I I I I	1 10000
Affiliation		
G.A.R. (Post Name & No)	M.O.L.L.U.S.
W.R.C. (Corps Name & No		
SUVCW (Camp Name & No		
DUVCW (Tent Name & No		,
X Other: Rotary International		
Original Podication Data 1945 1955	Discount of the second	
Original Dedication Date 1945-1955 local paper's article that would have information on the first	Please consult any/all t	newspaper archives for a er facts on the memorial.
Please submit a copy of your findings with full identification	of the paper & date of publication.	Thank you.
<u>Location</u>		
The Memorial is <i>currently</i> located at:		
Street/Road address or site location Normal be	etween No Henderson & No Pacific(W89°31'52" N37°18'42")
City/Village Cape Girardeau Township	County _Cap	e Girardeau, MO
The front of the Memorial faces: North	South Eas	st X West
Government Body, Agency, or Individual Owner		
Name Unknown, is on median on Southeast Mo State Campus		
Street Address		
City	_ State Zip Cod	e
Contact Person	Telephone ()	
If the Memorial has been moved, please list t	former location(s)	
Not Applicaber		
Physical Details		
Material of Monument or base under a Sculpture or Cannon	= X Stone Concrete M	etal Undetermined
If known name specific material (color of granite	marble etc.) Grey Granit	

Material of the Sculpture = Stone Concrete Metal Undetermined If known, name specific material (color of granite, marble, etc.) not applicable If the Sculpture is of metal, is it solid cast or "hollow?"					
Material of Plaque or Historical Marker / Tablet = bronze					
Material of Cannon =BronzeIron - Consult known Ordnance Listing to confirm Markings on muzzle = N/a					
Markings on Left Trunion Right Trunion					
Markings on Left Trunion Right Trunion Is inert ammunition a part of the Memorial? If so, describe					
Approximate Dimensions (indicate unit of measure) - taken from tallest / widest points Monument or Base: Height 2 1/2 ft Width 3 feet Depth 2 1/2 feet or Diameter Sculpture: Height Width Depth or Diameter					
For Memorials with multiple Sculptures, please record this information on a separate sheet of paper for each statue and attach to this form. Please describe the "pose" of each statue and any weapons/implements involved (in case your photos become separated from this form). Thank you!					
Markings/Inscriptions (on stone-work / metal-work of monument, base, sculpture) Maker or Fabricator mark / name? If so, give name & location found					
The "Dedication Text" is formed: cut into material _X_ raised up from material face					
Record the text (indicate any separation if on different sides) Please use additional sheet if necessary. 1861 1873 FORT B STATE COLLEGE On this eminence northwest of the city Fort B, one of four Civil War fortifications in					
Cape Girardeau was erected by Federal Troops in 1861 to guard the Perryville and Jackson Roads. Its garrison fought in the Battle of					
Cape Girardeau [New Paragraph] During the Battle of Cape Girardeau, on 26 April,1863. In 1873 the site was chosen for the campus					
of Third District Normal School Now the Southeast Missouri State College					
Profile of Indian Chief atop plaque.					
Rotary International symbol at bottom.					
Environmental Setting					
The general vicinity and immediate locale surrounding a memorial can play a major role in its overall condition.)					
Type of Location Cemetery Park Plaza/Courtvard					
Courthouse X_ College Campus Traffic Circle X_ Library					

	Suburban (residentia Jrban / Metropolitan		
Immediate Locale (check as many as may apply) Industrial Street/Roadside within 20 feet Protected from the elements (canopy or enclosure, indoors) Protected from the public (fence or other barrier) Any other significant environmental factor			
Condition Information	ĝ.		
Structural Condition (check as many as may apply) The following section applies to Monuments with Sculpture including the base for Monuments with Cannon. Instability in the by a number of factors. Indicators may be obvious or subtle. base.	e, and Monuments <u>wit</u> e sculpture and its base	e can be detected	
	Sculpture	Base	
If hollow, is the internal support unstable/exposed?	no	no	
(look for signs of exterior rust) Any evidence of structural instability?	no	no	
(look for cracked joints, missing mortar or caulking or plant growth) Any broken or missing parts? (look for elements (i.e., sword, musket, hands, arms, etc missing	no	no	
due to vandalism, fluctuating weather conditions, etc.) Any cracks, splits, breaks or holes? (also look for signs of uneven stress & weakness in the material)	no	no	
Surface Appearance (check as many as may apply)	Sculpture	Base	
Black crusting			
White crusting Etched, pitted, or otherwise corroded (on metal)		-	
Metallic staining (run-off from copper, iron, etc.)			
Organic growth (moss, algae, lichen or vines)			
Chalky or powdery stone		-	
Granular eroding of stone Spalling of stone (surface splitting off)			
Droppings (bird, animal, insect remains)			
Other (e.g., spray paint graffiti) - Please describe			
Does water collect in recessed areas of the Memorial?	Yes X No	Unable to tell	

Surface Coating Does there appear to be a coating?	
	Yes X No Unable to determine
If known, identify type of coating.	
Gilded Painted Varnis	
Is the coating in good condition? Y	es No Unable to determine
Basic Surface Condition Assessment	(check one)
In your opinion, what is the general appe	earance or condition of the Memorial?
X Well maintained Would benefit from treatme	ent In urgent need of treatment Unable to determine
Overall Description	
	l condition & any concern not already touched on) .
Good Condition. Part of bronze plaque is partially in the ground or	over the bottom half of the Rotary Symbol) That should be uncovered to avoid
discoloration.	
Supplemental Background Infor	
In addition to your on-site survey, any addit	ional information you can provide on the described
Memorial will be welcomed. Please label e	ach account with its source (author, title, publisher,
previous consequation treatments, or effects	to the points listed on this questionnaire, plus any
previous conservation treatments - or efforts	to raise money for treatment. I nank you.
Inspector Identification	
Date of On-site Survey 19 June 2006	
Date of On-site Survey 19 June 2006 Your Name Walter E Busch, Commander, US Grant Camp	#68, Dept of Missouri
Your Name Waiter E Busch, Commander, US Grant Camp Address PO Box 509	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp	
Your Name Waiter E Busch, Commander, US Grant Camp Address PO Box 509	City Pilot Knob
Your Name Waiter E Busch, Commander, US Grant Camp Address PO Box 509	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 53663	City Pilot Knob
Your Name Waiter E Busch, Commander, US Grant Camp Address PO Box 509	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 53663	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to:	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to: Todd A. Shillington, PDC 15 Park Place	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to: Todd A. Shillington, PDC	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to: Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	City Pilot Knob
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to: Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	City Pilot Knob Telephone (314) 630-8407
Your Name Walter E Busch, Commander, US Grant Camp Address PO Box 509 State MO Zip Code 63663 Please send this completed form to: Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022 (585) 638-5929	City Pilot Knob Telephone (314) 630-8407

