## NATIONAL ORGANIZATION

## SONS OF UNION VETERANS OF THE CIVIL WAR

## **CIVIL WAR MEMORIAL ASSESSMENT FORM**

PLEASE:	
<ul> <li>Type or print, using a ball-point pen, when</li> </ul>	filling out this form. Legibility is critical.
<ul> <li>Do not guess at the information. An answer</li> </ul>	
<ul> <li>Include a photograph of each viewable side ar</li> </ul>	
	- Thank You.
Type of Memorial	à
Monument with Sculpture	Monument with Cannon
Monument without Sculpture	X Historical Marker Plaque
<u>Affiliation</u>	
G.A.R. (Post Name & No	)M.O.L.L.U.S.
W.R.C. (Corps Name & No	Other Allied Order
SUVCW (Camp Name & No	) (Please describe below)
DUVCW (Tent Name & No	)
X Other: City of Cape Girardeau in conjunction with community	
Original Dedication Date May 6, 2006  ocal paper's article that would have information on the first delease submit a copy of your findings with full identification of	edication ceremony and/or other facts on the memorial.
Location	
The Memorial is currently located at:	
Street/Road address or site location Fort D Park,	
City/Village Cape Girardeau Township	County Cape Girardeau, MO
The front of the Memorial faces: North	South X East West
Government Body, Agency, or Individual Owner (o	of private cemetery that Memorial is located in)
Name City of Cape Girardeau	D - 1 (D)
Street Address A.C. Brase Arena 410 Kiwanis Drive	
Cape Girardeau,	State MO Zip Code 63701
Contact Person Dan Muser	Telephone ( 573 ) 335-5421
f the Memorial has been moved, please list for	mer location(s)
New Historic Marker	

Physical Details

Material of Monument or base under a Sculpture or Cannon = \_\_Stone \_\_ Concrete X Metal \_\_ Undetermined If known, name specific material (color of granite, marble, etc.)


Material of the Sculpture = Stone Conditions of the Sculpture = Stone Conditions of the Sculpture is of metal, is it solid cast or "hollow the Sculpture is of m	ble, etc.) not applicable
Material of Plaque or Historical Marker / Tablet =	metal stand with composite plastic face
Material of Cannon =BronzeIron - Cons Markings on muzzle = N/a	
Markings on Left Trunion	Right Trunion
Markings on Left Trunion	If so, describe
Approximate Dimensione (indicate unit of	è
Approximate Dimensions (indicate unit of meas Monument or Base: Height 4ft Width 24 in	Depth 24 in or Diameter
Monument or Base: Height 4ft Width 24 in Sculpture: Height Width	Depth or Diameter
For Memorials with multiple Sculptures, please sheet of paper for each statue and attach to this each statue and any weapons/implements inv separated from this form). Thank you!	form. Please describe the "pose" of
Markings/Inscriptions (on stone-work / metal-work / maker or Fabricator mark / name? If so, give name	rk of monument, base, sculpture) e & location found
The "Dedication Text" is formed: cut into mate	) Please use additional sheet if necessary.
	r under attack, boredom and disease were the biggest
enemies of the soldiers serving at Fort D. Soldiers passed their spare time rea	ding, writing letters, playing cards, sewing, gambling or
playing music. Games played inlouded baseball and pitching horsesho	S. [New Paragraph] In one recorded episode at Fort
D, soldiers constructed wooden bowling pins from blocks of wood. They then use	132-pound cannonballs as bowlling balls on a makeshift
wooden-floored bowling alley. One of these soldiers, Benjamin Radford gave strength to our arms.	, commented "They were effective, when hit, and
Courtesy of the Cape Girardeau Convention and Visitor Bureau and the City of Cape	Girardeau Parks and Recreation Department
Environmental Setting  The general vicinity and immediate locale surrounding a memorial	can play a major role in its overall condition.)
Type of Location	
CemeteryX Park	Plaza/Courtyard
"Town Square" Post Office	
Municipal Building State Cap	
Courthouse College Ca	ampus
Traffic Circle Library	

General Vicinity		
Rural (low population, open land)  X Town	_ Suburban (residential, r _ Urban / Metropolitan	near city)
Immediate Locale (check as many as may apply)  Industrial Street/Roadside within 20 feet Protected from the elements (canopy or enclosed protected from the public (fence or other barried Any other significant environmental factor	Commercial Tree Covered (overhang sure, indoors) er)	jing branches)
Condition Information	:	
Structural Condition (check as many as may appropriate following section applies to Monuments with Sculp including the base for Monuments with Cannon. Instability in by a number of factors. Indicators may be obvious or subbase.	uture, and Monuments without the sculpture and its base ca	in be detected
	Sculpture	Base
If hollow, is the internal support unstable/exposed? (look for signs of exterior rust)	-	
Any evidence of structural instability?  (look for cracked joints, missing mortar or caulking or plant grow	<del></del>	
Any broken or missing parts?  (look for elements (i.e., sword, musket, hands, arms, etc missi due to vandalism, fluctuating weather conditions, etc.)		
Any cracks, splits, breaks or holes?  (also look for signs of uneven stress & weakness in the material)		
Surface Appearance (check as many as may app	ly) Sculpture	Base
Black crusting		
White crusting Etched, pitted, or otherwise corroded (on metal)	-	
Metallic staining (run-off from copper, iron, etc.)	Annual Control of the	-
Organic growth (moss, algae, lichen or vines)		
Chalky or powdery stone		
Granular eroding of stone		-
Spalling of stone (surface splitting off) Droppings (bird, animal, insect remains)		-
Other (e.g., spray paint graffiti) - Please describe		
The marker is new as of 2006		
Does water collect in recessed areas of the Memorial?	Yes _X_NoU	nable to tell

Does there appear to be a coating?YesXNoUnable to determine If known, identify type of coatingGildedPaintedVarnishedWaxedUnable to determine Is the coating in good condition?YesNoUnable to determine Is the coating in good condition?YesNoUnable to determine Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memorial?	Surface Coating		
Gilded Painted Varnished Waxed Unable to determine Is the coating in good condition? Yes No Unable to determine Basic Surface Condition Assessment (check one)  In your opinion, what is the general appearance or condition of the Memorial?  X Well maintained Would benefit from treatment in urgent need of treatment Unable to determine  Overall Description  Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  Reinspection in 5 years will tell whether this historic marker will need maintainece  Supplemental Background Information  In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address Po Box 509 City Plat Knob  State MO Zip Code 60083 Telephone (314) 600-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place Holley, NY 14470-1022	Does there appear to be a coating?	_ Yes _X No	Unable to determine
Is the coating in good condition?YesNoUnable to determine  Basic Surface Condition Assessment (check one) In your opinion, what is the general appearance or condition of the Memorial?		hed Waxe	d Unable to determine
In your opinion, what is the general appearance or condition of the Memorial?  X Well maintainedWould benefit from treatment In urgent need of treatment Unable to determine  Overall Description  Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  Reinspection in 5 years will tell whether this historic marker will need maintainece  Supplemental Background Information  In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2005  Your Name		-	
In your opinion, what is the general appearance or condition of the Memorial?  X Well maintainedWould benefit from treatment In urgent need of treatment Unable to determine  Overall Description  Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  Reinspection in 5 years will tell whether this historic marker will need maintainece  Supplemental Background Information  In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2005  Your Name	Pacie Surface Condition Accessment	/ -tt \	
Overall Description  Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  Reinspection in 5 years will tell whether this historic marker will need maintainece  Supplemental Background Information  In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter EBusch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Pilot Knob  State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 144470-1022	In your opinion, what is the general appear	(Check <u>one)</u>	ion of the Mamorial?
Overall Description Briefly describe the Memorial (affiliation / overall condition & any concern not already touched on).  Reinspection in 5 years will tell whether this historic marker will need maintainece  Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification Date of On-site Survey 19 June 2006 Your Name Walter Busch, Commander, US Grant Camp #68, Dept of Missouri Address PO Box 509 City Pilot Knob State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	X Well maintained Would benefit from treatme	ent In urgent need	d of treatment Unable to determine
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification Date of On-site Survey 19 June 2006 Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri Address Po Box 509 City Pilot Knob State No Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022		0	
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Plot Knob  State MO Zip Code 63883 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022		l aandition D	
Supplemental Background Information In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Plot Knob  State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	Reinspection in 5 years will tell whether this historic marker will nee	I CONDITION & any cor	ncern not already touched on).
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022		A Maritaniese	
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022			
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022			
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022			
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022			
In addition to your on-site survey, any additional information you can provide on the described Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO BOX 509 City Pliot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022	Supplemental Packaraund Info		
Memorial will be welcomed. Please label each account with its source (author, title, publisher, date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509  State MO Zip Code 63863  Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	In addition to your on site survey, any addition	<u>nation</u>	
date, pages). Topics include any reference to the points listed on this questionnaire, plus any previous conservation treatments - or efforts to raise money for treatment. Thank you.  Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Pilot Knob  State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	Memorial will be welcomed Please label e	ach account with i	ts source (author title publisher
Inspector Identification  Date of On-site Survey 19 June 2006  Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Pilot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	date, pages). Topics include any reference	to the points liste	d on this questionnaire, publisher,
Date of On-site Survey 19 June 2006 Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri Address PO Box 509 City Pilot Knob State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	previous conservation treatments - or efforts	to raise money for	treatment. Thank you.
Date of On-site Survey 19 June 2006 Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri Address PO Box 509 City Pilot Knob State MO Zip Code 63863 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022	Increator Identification		
Your Name Walter E Busch, Commander, US Grant Camp #68, Dept of Missouri  Address PO Box 509 City Pilot Knob  State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022			
Address PO Box 509 City Pilot Knob State MO Zip Code 63663 Telephone (314) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022		#60 Doot of Minorari	
State Mo Zip Code 63863 Telephone ( 314 ) 630-8407  Please send this completed form to:  Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022			its Distinct
Please send this completed form to:  Todd A. Shillington, PDC  15 Park Place  Holley, NY 14470-1022			
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022		receptione (	314 ) 030-0407
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022			
Todd A. Shillington, PDC 15 Park Place Holley, NY 14470-1022			
15 Park Place Holley, NY 14470-1022	Please send this completed form to:		
15 Park Place Holley, NY 14470-1022	T 114 OF W. ( DD 0		
Holley, NY 14470-1022			
(585) 638-5929	15 Park Place		
	15 Park Place Holley, NY 14470-1022		
	15 Park Place Holley, NY 14470-1022		
	15 Park Place Holley, NY 14470-1022		
Thank you for your help, and attention to detail.	15 Park Place Holley, NY 14470-1022 (585) 638-5929		

> This form may be photocopied.

Sons of Union Veterans of the Civil War National Civil War Memorials Committee



LOCUST ST - CAPE GIRARDEAU MO

Untitled 1 Page 1 of 1

